

10/646,855

WEST Search History

DATE: Friday, August 24, 2007

<u>Hide?</u>	<u>Set</u>	<u>Name</u>	<u>Query</u>	<u>Hit Count</u>
			<i>DB=PGPB,USPT; PLUR=YES; OP=OR</i>	
<input type="checkbox"/>		L32	I31 or I30	349
<input type="checkbox"/>		L31	(I28 or I27) not L30	143
<input type="checkbox"/>		L30	I29 or I25	206
<input type="checkbox"/>		L29	L28 not I25	9
<input type="checkbox"/>		L28	I22 and passivation	116
<input type="checkbox"/>		L27	L26 not I25	143
<input type="checkbox"/>		L26	((cr or chromium) adj2 (plate or plated or plating)) and (chromate or "chromium oxide" or "chromium trioxide" or "chromium tri-oxide" or "cr tri-oxide" or "cr trioxide" or cr2o3 or "cr.sub.2o.sub.3") and "surface roughness"	159
<input type="checkbox"/>		L25	I23 or I11	197
<input type="checkbox"/>		L24	L23 not I11	2
<input type="checkbox"/>		L23	I2 and L22	18
<input type="checkbox"/>		L22	((cr or chromium)) and (chromate or "chromium oxide" or "chromium trioxide" or "chromium tri-oxide" or "cr tri-oxide" or "cr trioxide" or cr2o3 or "cr.sub.2o.sub.3") and "surface roughness"	2700
			<i>DB=EPAB,JPAB,DWPI; PLUR=YES; OP=OR</i>	
<input type="checkbox"/>		L21	I19 or I16	161
<input type="checkbox"/>		L20	L19 not I16	44
<input type="checkbox"/>		L19	((cr or chromium)) and (chromate or "chromium oxide" or "chromium trioxide" or "chromium tri-oxide" or "cr tri-oxide" or "cr trioxide" or cr2o3 or "cr.sub.2o.sub.3") and "surface roughness"	161
<input type="checkbox"/>		L18	L17 not I16	0
<input type="checkbox"/>		L17	((cr or chromium) adj2 (plate or plating or plated)) and (chromate or "chromium oxide" or "chromium trioxide" or "chromium tri-oxide" or "cr tri-oxide" or "cr trioxide" or cr2o3 or "cr.sub.2o.sub.3") and "surface roughness"	8
<input type="checkbox"/>		L16	I1 or I15	117
<input type="checkbox"/>		L15	L14 not I1	9
<input type="checkbox"/>		L14	chromium and (chromate or "chromium oxide" or cr2o3 or "cr.sub.2o.sub.3") and "surface roughness"	117
			<i>DB=PGPB,USPT; PLUR=YES; OP=OR</i>	
<input type="checkbox"/>		L13	L12 and @pd > 20070307	22
<input type="checkbox"/>		L12	L11 and @pd > 20060622	40
<input type="checkbox"/>		L11	L10 or L9 or L8 or L7	195

<input type="checkbox"/>	L10	4520077[uref]	4
<input type="checkbox"/>	L9	L8 not L7	101
<input type="checkbox"/>	L8	(chromium and (chromate or "chromium oxide") and "surface roughness") and passivation	107
<input type="checkbox"/>	L7	L6 or L3	90
<input type="checkbox"/>	L6	L4 not L3	16
<input type="checkbox"/>	L5	L4 not 3	0
<input type="checkbox"/>	L4	(chromium and (chromate or "chromium oxide") and "surface roughness") and L2	16
<input type="checkbox"/>	L3	(chromium and (chromate or "chromium oxide") and "surface roughness").clm.	74
<input type="checkbox"/>	L2	(427/331 or 427/337 or 427/372.2 or 427/377 or 427/383.1 or 427/383.3 or 427/383.7)[CCLS]	5901
	<i>DB=EPAB,JPAB,DWPI; PLUR=YES; OP=OR</i>		
<input type="checkbox"/>	L1	chromium and (chromate or "chromium oxide") and "surface roughness"	108

END OF SEARCH HISTORY